





M10

R0,80

6,50

$\phi 6$

14

4

SCHNITT B-B

0,50 X 45°

1 X 45°

0,50 X 45°

$\phi 14$

$\phi 52$







