



$\phi 10,70$


0,50 X 45°

$\phi 20$


$\phi 10,60$



4,70



SCHNITT A-A



2 X 45°

$\phi 60$

R21,20

